

Pr ty kwadratowe według DIN 1014

| wymiar | S355J2G3 / S355JO 18G2A | C45 gat. 45 | C60 gat. 60 | 16/ 20MnCrS5 16/ 20HG | 42CrMo4S4V 40HM ulepsz. |
|-------------|-------------------------------|----------------|----------------|--------------------------|----------------------------|
| kwadrat 10 | ● | | | | |
| kwadrat 12 | ● | ● | | | |
| kwadrat 14 | ● | | | | |
| kwadrat 15 | ● | ● | | | |
| kwadrat 16 | ● | ● | ● | | ● |
| kwadrat 18 | ● | ● | | | |
| kwadrat 20 | ● | ● | | ● | ● |
| kwadrat 22 | ● | ● | | | |
| kwadrat 25 | ● | ● | | ● | ● |
| kwadrat 28 | | ● | | | |
| kwadrat 30 | ● | ● | ● | ● | ● |
| kwadrat 32 | ● | ● | | ● | ● |
| kwadrat 35 | ● | ● | ● | ● | ● |
| kwadrat 38 | ● | ● | | | |
| kwadrat 40 | ● | ● | ● | ● | ● |
| kwadrat 45 | ● | ● | ● | ● | ● |
| kwadrat 50 | ● | ● | ● | ● | ● |
| kwadrat 55 | ● | ● | ● | ● | ● |
| kwadrat 60 | ● | ● | ● | ● | ● |
| kwadrat 65 | ● | ● | ● | ● | ● |
| kwadrat 70 | ● | ● | ● | ● | ● |
| kwadrat 75 | ● | ● | | ● | ● |
| kwadrat 80 | ● | ● | ● | ● | ● |
| kwadrat 85 | ● | ● | | ● | ● |
| kwadrat 90 | ● | ● | ● | ● | ● |
| kwadrat 95 | | ● | | | |
| kwadrat 100 | ● | ● | ● | ● | ● |
| kwadrat 110 | ● | ● | ● | ● | ● |
| kwadrat 120 | ● | ● | ● | ● | ● |
| kwadrat 130 | ● | ● | ● | ● | ● |
| kwadrat 140 | ● | ● | ● | ● | ● |
| kwadrat 150 | ● | ● | | ● | ● |
| kwadrat 160 | ● | ● | | ● | ● |
| kwadrat 170 | ● | ● | | | |
| kwadrat 180 | ● | ● | | ● | ● |
| kwadrat 190 | ● | ● | | | |
| kwadrat 200 | ● | ● | | ● | ● |
| kwadrat 210 | ● | ● | | | |
| kwadrat 220 | ● | ● | | | |
| kwadrat 230 | ● | ● | | | |
| kwadrat 240 | ● | ● | | | ● |
| kwadrat 250 | ● | ● | | | |
| kwadrat 260 | | ● | | ● | ● |
| kwadrat 280 | | | | ● | |
| kwadrat 290 | | ● | | | |
| kwadrat 300 | | | | | ● |

KONTAKT
PRIMO-STAL Sp z o.o.
ul. Słowackiego 6

59-550 Wojcieszów
tel. +48 75 75 12 665
e-mail. biuro@primo-stal.com